




A	B	C		D
1	N100-120	420	397	1/3
2	N100-121	420	397	1/3
3	N100-220	1497	402	1/3
	N100-219			
4	N100-221	1530	420	1/3
5	N100-313	489	397	1/3
6	N100-411	1497	60	1/3
7	N100-911	1507	429	1/3
8	N100-001	483	196	2/3
9	N100-002	414	482	2/3
10	N100-102	464	420	2/3
11	N100-119	464	420	2/3
12	N100-501	350	120	2/3
13	N100-502	350	120	2/3
14	N100-503A	431	120	2/3
15	N100-901	446	350	2/3





GERBOR.KIEV.UA





3x c818	9x e2 Ø 6,3x13 mm	8x p51 Ø3,5x15 mm	1x z1	15x l2	16x r1 Ø15x12 mm #16	16x r42	20x f1 Ø8x30 mm
2x w207/1 350 mm	2x w207/2 350 mm	14x e1 Ø7x50 mm	6x p140 Ø3,5x12 mm	6x e3 Ø6x13 mm	4x e32 Ø5x50 mm	2x d5 Ø6,3x15 mm	12x s2 Ø16
6x p1 Ø3,5x13 mm	4x a27	4x b13	20x p38 Ø3,5x16 mm	2x k129	1x k38 ⁷	1x k38 ³	






§2




3



4



5



6

