


























A	B	C	D	
1	S56-116N	1928	591	1/6
2	S56-117N	1928	591	1/6
3	S56-958N	1938	259	1/6
4	Lh-1922	1922	14	1/6
5	S56-213N	1061	591	2/6
6	S56-214N	1061	591	2/6
7	S56-308N	1028	571	2/6
8	S56-401	886	80	2/6
9	S56-482N	1028	200	2/6
10	Dr-1022	1022	24	2/6
11	S56-572N	1062	80	3/6
12	S56-576N	1962	80	3/6
13	S56-454N	960	80	4/6
14	S56-457N	562	80	4/6
15	S56-458N	562	80	4/6
16	S56-018	1796	466	5/6





1







2




3



4



5



6

