





A	B	C	D
1	N100-209	1412	402
	N100-207		1/4
2	N100-208	1445	420
3	N100-304	460	361
4	N100-405	1412	60
5	N100-406	460	60
6	N100-505	402	120
7	N100-109	816	420
8	N100-110	816	420
9	N100-111	772	397
10	N100-112	772	397
11	N100-501	350	120
12	N100-502	350	120
13	N100-905	417	350
14	N100-006	766	454
15	N100-007	766	454
16	N100-008	454	175
17	N100-906	781	473
18	N100-418	460	60





6x c818	30x s2	8x p51	1x z1	18x l2	34x r1	34x r42	34x f1
8x w207/1	8x w207/2	14x e1	24x p140	24x e3	16x e32	10x n108	10x p55
12x p1	4x a27	4x b13	20x p38	2x k129	1x k38 ⁷	1x k38 ³	9x e2


1







2




3



4



5



6

