







A	B	C		D
1	N100-113	1968	420	1/4
2	N100-114	1968	420	1/4
3	N100-908	1978	560	1/4
4	N100-210	583	421	2/4
	N100-228			
5	N100-211	583	421	2/4
6	N100-305	550	353	2/4
7	N100-306	550	400	2/4
8	N100-307	550	353	2/4
9	N100-408	550	60	2/4
10	N100-009	1526	544	3/4
11	N100-010	196	544	3/4
12	N100-501	350	120	3/4
13	N100-502	350	120	3/4
14	N100-506	492	120	3/4
15	N100-907	507	350	3/4





3x c818	1x d5 Ø6,3x15 mm	6x p51 Ø3,5x15 mm	1x z1	20x l2	18x r1 Ø15x12 mm #16	18x r42	18x f1 Ø8x30 mm
4x w207/1 350 mm	4x w207/2 350 mm	8x e1 Ø7x50 mm	12x p140 Ø3,5x12 mm	12x e3 Ø6x13 mm	8x e32 Ø5x50 mm	12x d1 Ø5x17 mm	12x s2 Ø16
8x p1 Ø3,5x13 mm	3x a27	3x b13	20x p38 Ø3,5x16 mm	2x k129	6x s4 Ø5	1x n261/1	6x e2 Ø6,3x13 mm



1






2




3



4



5



6

