





A	B	C	D	
1	N100-124	1968	580	1/5
2	N100-125	1968	580	1/5
3	N100-126	1532	560	1/5
4	N100-517	500	120	1/5
5	N100-916	1550	474	1/5
6	N100-225	974	581	2/5
	N100-227			
7	N100-226	974	581	2/5
8	N100-315	462.5	513	2/5
9	N100-316	462.5	513	2/5
10	N100-317	941	560	2/5
11	N100-318	462.5	513	2/5
12	N100-915	898	500	2/5
13	Dr-456	456	24	2/5
14	N100-015	196	934	3/5
15	N100-410	941	60	3/5
16	N100-416	941	420	3/5
17	N100-515	883	120	3/5
18	N100-518	500	120	3/5
19	N100-019	1526	456	4/5
20	N100-419	941	60	3/5



4x c818	2x Ø6,3x15 mm d5	12x Ø3,5x15 mm p51	1x z1	16x l2	26x Ø15x12 mm #16 r1	26x r42	32x Ø8x30 mm f1
4x 500 mm w210/1	4x 500 mm w210/2	14x Ø7x50 mm e1	16x Ø3,5x12 mm p140	12x Ø6x13 mm e3	8x Ø5x50 mm e32	8x Ø5x17 mm d1	18x Ø16 s2
8x Ø3,5x13 mm p1	6x a27	6x b13	22x Ø3,5x16 mm p38	2x k129/1	6x 20x13x3,51 mm n108	6x Ø2,9x16 mm p55	1x n26/1
2x n1	2x Ø3,5x13 mm p1	2x 483 mm t17	4x Ø3,5x16 mm p25	12x Ø6,3x13 mm e2			


1

§2




2


§6




3



4



5



6

