







A	B	C		D
1	N100-010	196	544	1/4
2	N100-113	1968	420	1/4
3	N100-114	1968	420	1/4
4	N100-501	350	120	1/4
5	N100-502	350	120	1/4
6	N100-506	492	120	1/4
7	N100-907	507	350	1/4
8	N100-908	1978	560	1/4
9	N100-210	583	421	2/4
	N100-228			
10	N100-211	583	421	2/4
11	N100-305	550	353	2/4
12	N100-306	550	400	2/4
13	N100-307	550	353	2/4
14	N100-408	550	60	2/4
15	N100-011	1526	544	3/4




3x c818	1x Ø6,3x15 mm d5	6x Ø3,5x15 mm p51	1x z1	20x l2	18x Ø15x12 mm #16 r1	18x r42	18x Ø8x30 mm f1
4x 350 mm w207/1	4x 350 mm w207/2	8x Ø7x50 mm e1	12x Ø3,5x12 mm p140	12x Ø6x13 mm e3	8x Ø5x50 mm e32	12x Ø5x17 mm d1	12x Ø16 s2
8x Ø3,5x13 mm p1	3x a27	3x b13	20x Ø3,5x16 mm p38	2x k129	6x Ø5 s4	1x n261	6x Ø6,3x13 mm e2



1






2




3



4



5



6

