







A	B	C	D	
1	N98-126	1984	549	1/5
2	N98-127	1984	549	1/5
3	N98-916	1580	429	1/5
4	N98-019	846	160	2/5
5	N98-208	886	550	2/5
6	N98-323	852	490	2/5
7	N98-325	852	490	2/5
8	N98-405	852	490	2/5
9	N98-512	794	110	2/5
10	N98-717	60	852	2/5
11	N98-915	809	450	2/5
12	N98-128	1562	490	3/5
13	N98-321	418	480	3/5
14	N98-322	418	480	3/5
15	N98-324	418	475	3/5
16	N98-514	450	110	3/5
17	N98-515	450	110	3/5
18	N98-712	60	852	3/5
19	Dr-412	412	24	3/5
19	N98-022	1543	421	4/5










GERBOR KIEV.UA





12x f4x16 mm <b>p19</b>	23x ø16 <b>s2</b>	4x <b>k127</b>	2x ø3,5x16 mm <b>p38</b>	20x <b>l2</b>	41x ø15x12 mm #16 <b>r1</b>	41x <b>r42</b>	34x ø8x30 mm <b>f1</b>
4x 450 mm <b>w209/1</b>	4x 450 mm <b>w209/2</b>	6x <b>l1</b>	12x ø3,5x12 mm <b>p140</b>	12x ø6x13 mm <b>e3</b>	8x ø6,5x40 mm <b>f25</b>	6x 20x13x3,5x1mm <b>n108</b>	6x ø2,9x16 mm <b>p55</b>
6x <b>a43</b>	6x <b>b19</b>	12x ø3,5x15 mm <b>p51</b>	8x ø5x17 mm <b>d1</b>	2x 433 mm <b>t37</b>	4x ø3,5x16 mm <b>p25</b>	2x <b>n1</b>	2x ø3,5x13 mm <b>p1</b>



1





2 





3




# 4



# 5



# 6



# 7

