




A	B	C		D
1	N111-014	395	181	1/1
2	N111-118	562	430	1/1
3	N111-119	562	430	1/1
4	N111-209	400	450	1/1
5	N111-210	400	450	1/1
6	N111-411	562	367	1/1
7	N111-506	400	120	1/1
8	N111-507	400	120	1/1
9	N111-508	310	120	1/1
10	N111-911	325	400	1/1











GERBOR.KIEV.UA



12x φ5x50 mm e32	12x φ16 s2	16x φ15x12 mm #16 r1	16x r42	14x φ8x30 mm f1	6x φ2,9x16 mm p55	4x φ7x50 mm e1	1x z1
4x k26	16x φ3,5x16 mm p38	3x 400 mm w5\DR	3x 400 mm w5\CL	3x 400 mm w5\CR	3x 400 mm w5\DL	12x φ5x9 mm e19	18x φ6x13 mm e3
3x c831/1							





1




2




3



4



5



6

